


- W - LINE 1
- BL - LINE 2
- B - LINE 3
- R - COMMON X1
- O - COMMON X2
- W-B - MAINLINE COIL
- G-Y - GROUND



TO CONVERT WIRING FROM 440-480/3/60 OR 380-415/3/50 TO 208-240/3/60 OR 190-220/3/50 OPERATION, MOVE THE TWO PLUGS ON THE VOLTAGE CHANGE BOARD FROM THE LUGS MARKED HIGH VOLTS TO THE LUGS MARKED LOW VOLTS.

- ◆ DIODE
 - ⊞ SUPPRESSOR
 - FUSE
 - CONNECTOR
 - MECHANICAL INTERLOCK
 - TERMINAL
- B-BLACK
 - R-RED
 - W-WHITE
 - G-GREEN
 - BL-BLUE
 - BR-BROWN
 - L-LIGHT YELLOW
 - O-ORANGE
 - P-PURPLE